LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. ____ N. S., R. ____ E. W.	
2. PROPERTY CONTROLLING IN SECTION 17	,T. 33 N. S., R. 4 E. W.	13;6;4;9
3. MISCELLANEOUS PROPERTY IN SECTION ____	,T. ____ N. S., R. ____ E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 4, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

4

Drove 5/8" x 34" rerod w/RLS cap (buried 0.3')

6" Rock Elm clump	N85°E	52.00'
16" Elm (Green)	S30°E	83.61'
18" Cherry	N65°W	84.05'
Set cedar post w/loc tag	East	33'
Ctr N-S gravel road	East	5'±

9

Found "T" iron

P.Pole	N65°W	79.90'
8" Tri Rock Elm	S16°W	72.07'
Fd "T" iron	South	33.06'
Set cedar post w/loc tag	North	33'
Ctr E-W gravel road	North	6'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

13 - Fd. & accepted "T" iron for ctr. of SE¼ of Sec. 17.

6 - Establish ctr. of NE¼ of Sec. 17 per standard B.L.M. instructions.

4 - Establish SW corner of NE¼ of NW¼ of Sec. 17 per standard B.L.M. instructions.

9 - Fd. "T" iron by RLS, Larry Feindt for SE corner of SW¼ of NE¼ of Sec. 17. Fits E.A. Robinson survey of Sec. 17 (1902).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13

Fd. "T" iron w/RLS cap #3920 set cedar post w/loc tag

P. Pole	S42°E	53.55'
Fd "T" iron w/RLS cap #3920	S89°42'13"E	313.68'
Fd 1" pipe	N66°49'28"E	91.91'
10" Apple	N50°E	89.72

6

Drove 5/8" x 34" rerod w/RLS cap & set cedar post w/loc tag

12" Spruce	N06°E	14.7'
8" Maple	S32°E	40.8'
10" Cedar	S25°W	77.2'
Ctr N-S gravel trail	East	36'±

SIGNED BY Carl F. Roser 02-07-86 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET