LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 4 E. W.	E-8; D-7;
2. PROPERTY CONTROLLING IN SECTION 20	,T. 33 N. S., R. 4 E. W.	4; 1
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 3, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

E-8

Drove 1" x 42" pipe w/DNR cap & set cedar post

8" Tamarack	N52°E	28.0'
5" Maple	S70°E	9.6'
15" White Pine	S60°W	22.1'
12" Cedar	N64°W	31.1'

D-7

Fd 2" x 36" pipe, drove 1" x 42" pipe w/DNR cap inside & set cedar post

12" Cedar	N60°W	28.9'
8" Cedar	N26°E	21.4'
6" Ash	S32°E	9.3'
12" Ash	S48°W	28.4'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 - Fd. & accepted "T" iron w/RLS cap for SE corner of NW¼ of NW¼ of Sec. 20 as set by Larry Feindt. Larry estab. this cor. after discussions with C. Roser Spring 1985.

1 - Fd. & accepted well point for NE cor. of NW¼ of NW¼ of Sec. 20. Fits E.K. Robinson & E.A. Robinson survey data; Robinson notes call for "well point"

E-8 - Re-estab. E 1/4 corner of Sec. 20 equidistant & on line between NE & SE corners of Sec. 20.

D-7 - Fd. Schaaf 2" x 36" pipe monument for N 1/4 corner of Sec. 20. Fits E.K. Robinson 1897 & E.A. Robinson 1913 survey data.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4

Fd "T" iron w/cap #21566 & 25834 added cedar post w/loc tag

6" Ash	N65°W	24.8'
10" Maple	N55°E	12.6'
5" Maple	S70°E	9.0'

1

Found well point

16" Twin Maple	N56°E	39.81'
16" Twin Maple	S30°E	57.93'
18" Maple	S72°W	51.51'
Set cedar post w/loc tag	West	33'
Ctr N-S gravel rd	East	2'±
Old E-W fn (mostly down)	to west	

SIGNED BY Carl F. Roser 02-07-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET