LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 4 E. W.	C-11; C-10;
2. PROPERTY CONTROLLING IN SECTION 29	,T. 33 N. S., R. 4 E. W.	16;
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 6, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued

C-10

Found 1¼" pipe in gravel road intersection

25" Apple	N58°W	87.16'
10" Maple	N54°E	64.90'
*15" Maple	N72°E	41.90'
20" Maple	S26°E	55.90
Set ced post w/loc tag	East	33'

*M.FEINDT FACE NAIL.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

16 - Estab. E 1/8 Cor. on S. line of Sec. 29, mid-way & on line between S 1/4 Cor. & SE cor. of Sec. 29. Corner falls in ctr. of E-W gravel road.

C-11 - Found 1¼" pipe in road intersection E-W-N. Fits E.A. Robinson 1902 wit. & survey data of Sec. 29; Chandler Bk, pgs. 4-9.

C-10 - Found & accepted 1¼" pipe in "T" road intersection N-S-W (fn east) for 1/4 corner common to Sec's 29 & 30. Fits E.A. Robinson survey & sec. subd. of Sec 29, dated Jan. 1902; Chandler Bk, pgs. 4-9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

16

Drove 5/8" x 34" rerod w/RLS cap

5" Maple	S10°E	82.06'
P. Pole	S50°W	71.26'
8" Cedar	N16°W	73.85'
Set ced post w/loc tag	North	33'
E-W R.O.W. fn.	North	44'±
E-W R.O.W. fn.	South	45'±

C-11

Found 1¼" Pipe

*** 40" S. Maple	N52°W	36.72'
*** 30" S. Maple	N50°E	36.77'
24" Maple	S72°W	99.30'
*** P. Pole	S14°E	33.90'

*E.A.R. 1902 WIT.

***M.FEINDT WITS.

SIGNED BY Carl F. Roser 02-07-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET