LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 4 E. W.	D-11; F-11; G-9
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 6, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued

G-9

Fd. 1" pipe; replaced w/DNR mon. and set cedar post

7" Maple	S60°E	9.5'
6" Maple	S20°W	17.5'
10" Maple	S70°W	18.5'
8" Maple	N06°E	15.1'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11 - Fd. 1¼" pipe, buried 7", in approx. ctr. of E-W gravel road, & in line with N-S fn. to north. E-W R.O.W. fn. is 42'±S. Fn. Cor. (fn's N&W) is 34'±N. Fn. Cor. (fn's N&E) is 48'±N. Accepted fd. 1¼" pipe for 1/4 Cor. common to Sec's 29 & 32. Fits E.A. Robinson, 1902 survey & sec. subd. of Sec. 29, Chandler Bk., pgs. 4-9, on file at Jury Room in courthouse.

F-11 - Re-estab. S¼ Cor. Sec. 28 mid-way & on line between Sec. corners to E&W.

G-9 - Fd. & accepted 1" pipe for NE corner of Sec. 28. Fits corners & survey data east one mile by E.K. Robinson; dated Sept. 1881, Book 116, page 28.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11

Fd. 1¼" pipe, drove 5/8" x 17" rerod w/RLS cap inside

P. Pole	S66°W	122.46'
P. Pole	S64°E	87.07'
24" Elm stp	N02°E	79.51'
Set Cedar Post w/loc tag	South	33'

F-11

Set DNR Mon. & Cedar Post

6" Elm	N80°E	69.45'
22" Ash	N32°E	23.82'
22" Maple	N52°W	30.08'
5" Ironwood	South	100.93'
E-W,W-W fn. on ced. post	North	13.'
Ctr. E-W P. Pole's	South	47.'
Ctr. Gravel Rd. (SE'ly in curve)	South	70'±

SIGNED BY Carl F. Roser DATE 02-07-86

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028 (SEAL)

STATE OF MICHIGAN — CARL F. ROSER — LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ (CHIEF OF SURVEY PARTY) DATE _____

APPROVED AND SIGNED BY _____ (MICHIGAN REGISTERED LAND SURVEYOR) DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION. JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET