LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. _____ N. S., R. _____ E. W.	
2. PROPERTY CONTROLLING IN SECTION 18 28	T33N T. 33 N. S., R. R04W 4 E. W.	1 16; 15;
3. MISCELLANEOUS PROPERTY IN SECTION 18	T. 33 N. S., R. 4 E. W.	907.5' S. of B-6

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 5, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on December 5, 19 85, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued)

907.5 South of B-6

Drove 5/8" x 34" rerod w/RLS cap & set cedar post w/loc tag

6" Maple	N30°E	6.5'
8" Twin Maple	S50°E	23.1'
5" Maple	N30°W	14.3'

1 Sec. 18

Found 1" pipe; added RLS cap & set cedar post

3" Maple	N35°W	3.8'
3" Red Pine	S65°E	9.5'
11" Cherry in clump	S30°W	19.3'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

16 - Established SW corner of SE¼ of SE¼ of Section 28 per standard B.L.M. instructions.

15 - Establish SE corner of SW¼ of SW¼ of Sec. 28 per std. B.L.M. instructions. A cor. fn. post (fn's N&E) is 5'±E & 22'±N.

907.5' S. of B-6 - Drove 5/8" x 34" rerod record per state deed description: "55 rods (907.5') south of ctr. post in Section" (came south 907.5' from ctr. of sec. on N-S 1/4 line).

Sec 18 1 - Fd. 1" pipe by E.A. Robinson for NE cor. of frl. NW¼ of frl. NW¼ of Sec. 18 (fits prorated to G.L.O. plat-runout Sec.). See Chandler Bk., pg. 3, dated Dec. 1916.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

16

Drove 5/8" x 34" rerod w/RLS cap & set cedar post w/loc tag

3" Maple	N30°W	5.5'
2" Maple	N35°E	12.5'
5" Maple	N70°E	13.3'
5" Maple	Due South	14.5'
Ctr. E-W P. Pole's	South	45 '

15

Drove 5/8" x 34" rerod w/RLS cap

P. Pole	S68°E	139.53'
Cor fn post	N14°E	23.00'
Set ced post w/loc tag	South	39.5'
Ctr E-W gravel road	South	7'±

SIGNED BY Carl F. Roser 02-07-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET