# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF–: | LOCATED IN–: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 33 N. S., R. 4 E. W. | I-12; I-11; H-11 |
| 2. PROPERTY CONTROLLING IN SECTION | , T. N. S., R. E. W. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION | , T. N. S., R. E. W. | |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 23, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

H-11

Fd. 1¼" x 36" pipe; replaced w/DNR monument & set cedar post

| | | |
|---|---|---|
| 12" Ash | S60°E | 2.75' |
| 14" Maple | S16°W | 40.10' |
| 12" Maple | N80°W | 16.25' |
| 17" Maple | N06°W | 28.96' |
| Ctr. E-W Power Trans. Line | North | 85'± |
| Ctr. Power Service line | East | 18'± |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-12 - Fd. ½" rod driven inside old well point. E.K. Robinson & E.A. Robinson Notes call for well point; see Chandler Book, pgs. 27 & 39 (1905); notes on file in Jury Room at Gov't. Bldg.

I-11 - Fd. & accepted "T" iron for NE corner of Sec. 34. Corner falls in approx. intersection of gravel roads E-W-N and winding trail road south.

H-11 - Fd. & accepted old 1¼" x 36" pipe for N¼ Cor. of Sec. 34. Fits E.A. Robinson (1905) Sur. & Sec. Sub'n. of Sec. 34; see Chandler Book, pgs. 24-39, notes in Jury Room in Gov't. Bldg. An old cor. fn. post hole (fn's N&E) is 30'± North.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12

Fd. ½" rod w/RLS cap #20703 drive inside old well point

| | | |
|---|---|---|
| 28" Beech | N24°E | 35.25' |
| 18" Beech | N86°E | 29.65' |
| 20" Maple | S36°W | 49.42' |
| 12" Maple | N54°W | 52.85' |

I-11

Found "T" iron

| | | |
|---|---|---|
| 8" White Pine | N66°W | 71.20' |
| 24" Maple | N22°W | 79.53' |
| 25" Maple | N80°E | 116.42' |
| 36" Elm stp. | S80°W | 79.47' |

SIGNED BY Carl F. Roser 02-07-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET