LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	• •
I. PUBLIC LAND SURVEY	т. 33 🤻, к. 5	K-11,L-9,L-11,L-10	
2. PROPERTY CONTROLL- ING IN SECTION——	N. E. W. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	, T S., R E V.		
4. LOT NO, REC	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in I re-established, monumented, re- and rules therefore as required Bureau of Land Management or and 5 above were, in a field surv	ines 1 and 2 above were, in a monumented, recovered or rein the current manual of survey a decree of a court of law rey on	n field survey on <u>November</u> estored as expressed below and rey instructions of the United S by Furthermore, that the corner of 19, found, recovered, rest	of P.A. 74, Michigan P.A. of 1970, 6 , 19.81 , established, in conformance with regulations tates Department of the Interior, r points mentioned in lines 3, 4 cored, established or re-established ration for Land Surveyors or, by a
xXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	orvonereka xxxxxexen	ХАККХККИМИМИМ	
K-11			
Fd. R.R. iron T. Pole S40°E	32.50		
Fn. post East 30" W. Pine S20°E	26.40 90.00		
00 m			•
in Jury Room acro L-9 Reestablished N E & W. Corner for the cor. post (from the cor. post (from the cor. fits) L-10 Estab. center of the correction of monument for the correction of t	oss from Register of I/4 corner of Sec. 25 alls in swamp. R.R. rail, vertical, n's N-E-W). Put loca prior surveys in thi Sec. 25 at intersect ner S) is 6'± W. Creor corner and accessories established pipe Fd. narrow 6' pipe 14" Maple 14" Maple 46.1 9" Elm 24.0 5" Maple 17.9	Deeds - "Melrose", Pgs 5, equidistant & on lin , with about 3' above go ation tag on newer cord is area by E. A. Robins tion of 1/4 lines. Old eek crossing culvert is olished to perpetuate locating the L-11 Gauge R. R. Rail Drov Sloow 26.7 in S50°E 25.6 7" ! S74°W 21.3 lo" N78°E 28.2 lo" Set ti	pround, at SE cor. of old post that is 1' N of RR son. i irregular wire in trees 36'± east. Exposition of the corner: L-10 Ve 1" x 24" pipe w/RLS cap road. Maple S40°E 45.08 Maple S20°W 42.67 Maple N70°W 69.56 ced. post w/loc ag. South 33' pipe in conc. S88°15'F 47.95
SIGNED BY Carl 7.	Roser 01-12	P-82 DATE	AND OF MICES
SURVEYOR'S MICHIGAN RE	CISTRATION NO. 12	2028	CARL
FOR STATE AND UNITED S	STATES AGENCIES:		F. ROSER
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	SURVEYOR No. 12028
APPROVED AND SIGNED B	Y MICHIGAN REGISTERED	LAND SURVEYOR DATE_	NO. 12028 . S. T.
SURVEYOR'S MICHIGAN RI	•	M	ELROSE TOWNSHIP HARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1975