LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N., R. 5 W.	G-11, I-11
2. PROPERTY CONTROLLING IN SECTION 34	,T. 33 N., R. 5 W.	5, 4
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 8, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

C. Continued:

I-11

Set DNR mon. & ced. post

5" Maple	N60°W	7.4
5" Maple	N55°E	4.9
5" Maple	S35°E	36.0

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

5 Estab. NE cor. of SE1/4-NW1/4 of Sec. 34 per std. B.L.M. instructions.

4 Estab. NW cor. of SE1/4-NW1/4 of Sec. 34 per std. B.L.M. instructions.

G-11 Fd. 1" solid iron that fits E.A. Robinson's double proportion cor. as estab. in Jan. 1908; see old Co. Surveyors Records in jury room-"Melrose" pgs. 53 thru 59.

I-11 Reestab. NE cor. of Sec. 34 per E.A. Robinson survey, Jan. 1908. Robinson had both U.S. B.T.s; we restored the cor. based on his survey across corners to two miles west. See old Co. surveyors records in jury room across from Reg. of Deeds; "Melrose" Book, Pgs. 53 thru 59.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5

Set 5/8" x 36" rerod w/RLS cap & ced. post

8" Maple	S75°E	49.6
9" Maple (cluster)	S40°E	34.9
8" Maple (cluster)	S85°W	71.5
Fd. rerod	S81°07'E	31.65

4

Set 5/8" x 36" rerod w/RLS cap & ced. post.

3" Ironwood	N85°E	31.8
4" Ironwood	S45°E	35.2
8" Ash (cluster)	West	31.3
Fd. rerod	S57°E	16.1

G-11

Fd. 1" solid ir. (buried 0.8)

4" Cedar	S30°W	34.0
9" Tamarack	N70°W	82.8
Fd. 3/8" rerod	N	33.24
Fd 3/8" rerod	S	32.78
Set Ced. Post	S	33'

SIGNED BY Carl F. Roser 01-12-82 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR SEAL No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET