LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N., R. 5 W.	D-11,C-12,D-13,D-12
2. PROPERTY CONTROLLING IN SECTION ____	T. ____ N. S., R. ____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S., R. ____ E. W.	

4. LOT NO. ____, RECORDED PLAT ____

5. PRIVATE CLAIMS ____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 7, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. Continued: to U.S. & fits survey of Sec. 32 (N-S¼ line) by E.K. Robinson dated 1881.
D-12 Fd. 1" pipe surrounded by rocks for ctr of Sec. 32. Fits Sec. Sub'n of Sec. 32 by E.K. Robinson in 1881; See large brown liber No. 1 of Co. Surveyors Records, Pg. 299 at Court House.

C. Continued: D-12

Fd. 1" Pipe w/rocks around & set ced. post w/loc. tag.

7" Maple	N55°E	2.2
7" Maple	N65°W	12.1
6" Maple	S30°W	18.7
E-W tr. rd.	South	60'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11 Fd 2½ sq'd stk bottom that fits 1909 E.A. Robinson B.T. (20" Sug. now a stump, S53°E, 60.1'). Cor falls in N-S W. wire fn. remains. Fn cor, fn. remains N-S-W, is 6.5'N. Cor. fits very close to midway & on line between fd. Robinsons recovered NE & NW of Sec. 32; See E.K.R. notes 1878 & 1881, "Milrose", Pg. 68, which indicate he set the cor. S.P.; E.A.R. marked newer B.T. in 1909, "Melrose" Pg. 71.

C-12 Fd. odd shaped old farm iron surounded by stones that fits E.A. Robinson Wits (1901); Pg. 1 of Melrose Book; 4" Hemk. (now 23") S87 1/2E, 73 Links; cor fn. post (now down) S1°W, 47½ links. Cor. is in line with ctr of E-W sand two track County Rd. to E, & in SW'ly wheel track of irregular two track NW & SE. Fn. remains to east are north 19'± & fn. remains west are south 32'±.

D-13 Fd. 3/4" pipe & Wits tags by RLS L. Feindt. Cor. fits cor. position by single proportion

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11

Fd. stk. bottom; set DNR mon. & ced. post.

33" Oak	N80°W	41.90
10" Maple	N03°E	19.2
10" Maple	N50°E	7.8
7" Y. Birch	S75°E	14.8
N-S Trail rd. Due W		56'±

C-12

Fd. 1" x 15" iron pin with scythe blade along side (buried).

23" Hemlock	S88°E	47.89
31" Twn. Beech	N24°E	25.34
13" Maple	S04°W	57.62
28" Maple	N39°W	93.16
Set ced. post W/loc tag	W	16.5

D-13

Fd. 3/4" pipe; replaced w/DNR mon. & ced. post.

8" Maple (cluster)	S85°E	14.9
*8" Maple "	N55°E	15.07
*6" Maple "	S85°W	26.60
2" Pipe (flush w/ground)	N75°E	26.66

*=Old Wits w/cap #21566

SIGNED BY Carl F. Roser 01-12-82 DATE ____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

(SEAL) STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ DATE ____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ____ DATE ____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET