LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N., R. 5 W.	F-10, E-11, C-11
2. PROPERTY CONTROLLING IN SECTION 28	T. 33 N., R. 5 W.	7
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 25, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

C. Continued:

E-11

Fd. well pt. under large rock & added DNR mon. & ced. post

14" Oak	S84°W	48.4
10" Oak	N70°E	51.4
6" Ash	N8°E	52.3

Set DNR mon. on E side of well point

C-11

Fd. 2" pipe, added ced. post w/loc. tag

12" Maple	N45°W	9.2
10" Maple	N85°W	17.5
11" Oak	South	30.8
N-S trail road	West	118'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-10 Estab. center of Sec. 28 at intersection of one-quarter lines.

7 Estab. N 1/8 on E line of Sec. 28 per std. B.L.M. instructions.

E-11 Fd. well point, sandstone & pine stump Wit., N27°W, 70.0' per E.A. Robinson, Jan. 1908. E.A.R. had old stk & roots of U.S. B.T's. See old Co. surveyors Records in Jury Room across from Register of Deeds; "Melrose", Pg. 55.

C-11 Fd. & accepted 2" pipe at position of rotted-off cor. fn. post, fn. remains N-E-W. Fits survey by E. A. Robinson, 1916; see "Melrose" book, Pg. 95.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-10

Drove 7/8" x 18" solid iron rod

Set 5/8" x 36" rerod w/caps & ced Post N00°12'21"W 33.00

Set 5/8" x 36" rerod w/cap & ced. post S00°12'21"E 33.00

Ctr line E-W gravel rd. South 5'±

7

Drove 3/8" x 5/8" x48" iron w/RLS cap & set ced post

6" Cedar	N45°W	17.9
12" Tamarack	S62°W	33.0
14" W. Pine	S35°E	18.1
Ctr. R.R. tracks	N87°58'W	229.9'
Ctr. US-131	N87°58'W	414.4

SIGNED BY Carl F. Roser 01-12-82 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET