LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. 33 N., R. 5 W.	M-9, M-10, M-11, K-9
2. PROPERTY CONTROLLING IN SECTION _____	,T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	,T. _____ N. S., R. _____ E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on _____, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. Continued: East, 1/2 mile South, 2 miles West, 2 miles North. Corner falls on NW side of 14" Elm stump.

C. Continued:

K-9

Set 1" x 6' pipe w/DNR mon. cap 1 1/2' above grd & ced. post.

10" Maple	N55°W	32.9
6" Maple	N40°E	28.1
5" Maple	S80°E	17.8
7" Cedar	S10°E	21.5

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

M-9 Fd. and accepted old Well Point for NE cor. of Sec. 25. Old M. Schaaf mon. (buried in old N-S horse & buggy days Twp. Rd. grade) was not accepted. Well Point looks older than Schaaf Mon. Schaaf notes he had B.T. sites (Maples) but they would fall in old road which is in Cut Section. Well Point previously recovered & Wit. by M. Feindt. Well point fits U.S. tie north to enter swp. 4 chains (264' Rec. & Mea.) & north to stream 15 L. C.NW, 9.5 chains (627' Rec. & Mea.).

M-10 Fd. & accepted 1" pipe for E1/4 of Sec. 25; cor. previously used by RLS Mary Feindt. Fence to north is 2'± west.

M-11 Fd. Mary Feindt's 3/4" pipe over 1 1/4" pipe w/conc. base (Schaaf Mon.). Corner fn. post (fn. down to S & wire in trees to W) is S15°W, 66'±

K-9 Reestab. NW cor. of Sec. 25 by double proportion to U.S. (G.L.O.); to fd. cors. 1 mile

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9

Fd. Well Point; added sq'd ced. guard post w/loc tag.

Fd. Schaaf mon. (buried)	N05°E	12.65
*14" Maple	N70°E	22.70
*4" Maple	S50°E	17.75
*8" Maple	S82°W	16.30
Old N-S E'ly R.O.W. fn.	East	22'±

*=Old Wits

M-10

Fd. 1" pipe w/RLS cap #3920

4" Maple	S24°E	56.2
7" Ash	S10°W	38.0
3" Maple	N45°W	32.8
Set ced. post w/loc tag	North	27'
Ctr. E-W gravel rd.	South	6'±

M-11

Fd. 1 1/4" pipe w/cone base & 3/4" pipe w/RLS cap #3920; replaced with DNR mon. & set ced. post w/loc. tag.

13" Ash	N25°E	15.5'
8" Maple	S20°E	3.0'
7" Maple	N64°W	15.5'

SIGNED BY Carl F. Roser 01-12-82 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET