## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. <u>33</u> N. R. <u>5</u> W	K-7. K-10	
2. PROPERTY CONTROLL- 23	,T. 33 N; R. 5 V.	7, 3,	
3. MISCELLANEOUS PROPERTY IN SECTION	N. S., R. E. W.		
4. LOT NO , RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re- and rules therefore as required in Bureau of Land Management or and 5 above were, in a field surve as expressed below and in confor Decree of a Court of law:	nonumented, recovered or reson the current manual of survey by a decree of a court of law.  Ey on	tored as expressed below and y instructions of the United St Furthermore, that the corner 19, found, recovered, restolichigan State Board of Registra	P.A. 74, Michigan P.A. of 1970, 25 , 1981 , established, in conformance with regulations ates Department of the Interior, points mentioned in lines 3, 4 ared, established or re-established ation for Land Surveyors or, by a sying flat, WNW, 161 & a
1/4" rod bent over   accept Mary's 1/4 cc C. Continued:	nnw 10° & also culver orner.	t (CMP) is 40'I W of M	lary's point. Could not
Drove 5/8" x 3 8" Cedar 9" Cedar 12" Cedar 7" Cedar 7" Cedar 8. Description of corner evidence 7 Estab. N 1/8 corner K-10 Reestab. NW corner of K-10 Reestab. W 1/4 Sec. SW cor. of Sec. 25 & Robinson (1906) who Mitchell logging rai not fd. that the U.S cor. of Sec. 25 was ler Twp. from his we C. Description of monument for 3 Set 5/8" x 36" rerod w/f cap & ced. post w/loc. 7" Oak Due E 7" Maple S30°W 7" Maple N60°W Trail rd. NW & SE East 1	S75°E 2 S30°E 3. S35°W 1. N60°W e found and/or method applie 1 E. line of Sec. 23 Ctr 20' stream Csc. N on W line of Sec. 23 of Sec. 24 by double 25 on old estab. 1/4 dour reestab. NW cor made a survey of Receilroad and he notes to 1/4 post for W 1/4 "Location not known" corner and accessories establis RLS Set DNR mon. It is a stablis RLS Set DNR mon. It is a stablished the stablished	e 3/4" x 42" pipe & sel.5  2.4  4.4  9.6  In restoring or re-establishing per std. B.L.M. instruction in the second of the second of the second for Hwy. along the second for	corner: ctions. Ctr. 20' stream, prayel rd. West 1010'±. uctions. L.O.). In straight line bet. fd. by Co. Surveyor E.A. bed of old Cobb's & ors. that were lost or found" and that the NW indicates rd. E to Chand- dt. fd. an ir. bar (knocked  K-10  x 3' rerod w/RLS cap r N85°E 81.02 r N45°E 76.77 r S10°W 33.50 d w/RLS cap & ced. Loc tag. N00°03'E 33.00 eindt's small k. S87°56'E 45.62
SIGNED BY Carl 7.			CARL CARL
SURVEYOR'S MICHIGAN REC	Fall to the second of the seco	· .	CARL F. ROSER
FOR STATE AND UNITED ST SIGNED BY		ነንልጥድ	SURVEYOR No.
APPROVED AND SIGNED BY	CHIEF OF SURVEY PARTY  MICHIGAN REGISTERED LAN	DATE DATE	F. ROSER LAND SURVEYOR NO. 12028 AND SURVEYOR AND SURVEYO
SURVEYOR'S MICHIGAN REG	ISTRATION NO.		ROSE TOWNSHIP RLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1975