LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 5 E. W.	K-8, J-9, I-8
2. PROPERTY CONTROLLING IN SECTION 21	,T. 33 N. S., R. 5 E. W.	6,
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 25, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

I-8

Set DNR Mon. & Cedar Post

6" Maple (Cluster)	S80°E	29.0
5" Maple	S10°E	39.5
6" Maple	S25°W	54.1

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

6 Established ctr. of NE 1/4 of Sec. 21 per std. B.L.M. instructions.
K-8 Reestab. E1/4 cor. of Sec. 23, midway and on line between the SE & NE cor's. of S-23.
J-9 Reestab. South 1/4 corner of Sec. 23, midway and on line between the SE & SW cor's. of Sec. 23.
I-8 Reestab. W 1/4 cor. of Sec. 23, midway and on line between the NW & SW cor's. of Sec. 23.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6

Set 5/8" x 36" rerod w/RLS cap & ced. post

10" Maple	N65°E	6.4
9" Maple	S30°E	17.4
5" Maple	S85°W	17.2
Fd. T Ir. at old cor. Fn. post hole	N00°51'W	19.7

K-8

Set DNR Mon & Ced. Post

5" Maple	N45°E	22.8
6" Cedar	S80°W	12.5
7" Cedar	S15°E	23.3
N-S trail rd. West		980'±

J-9

Set DNR Mon & Ced. post

6" Maple	N80°E	11.5
6" Maple	N45°W	17.5
8" Maple (twin)	S85°W	28.9

SIGNED BY Carl F. Roser 01-12-82 DATE _____

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION. JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET