LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 5 E. W.	E-9, E-8
2. PROPERTY CONTROLLING IN SECTION 21	,T. 33 N. S., R. 5 E. W.	1, 2
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 19, 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

2

Set 5/8" x 36" rerod w/RLS cap & Cedar Post

5" Maple	N65°W	34.8
12" Maple	S70°W	45.6
6" Maple	S15°W	17.9
E-W fn.	North	4'±

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-9 Restored NE cor. of Sec. 29 per two E.A. Robinson Wit. (May 1909); Cedar stump 12 S68°E 45.5' & Tamarack 14"(now a stump) S57W 31.7'. Cor. fits 1909 stream tie to South 270'± from E.A.R. random.

E-8 Restored E ¼ cor. of Sec. 20 in line with old quarter line fence to East & 29'W of R.O.W. fence to North which fits prorated distance to Robinson across W½ & ctr. of Sec. 20 and also fits Robinson's distance very close for ½ mile to N & S. Irregular wire in trees to S & W. See survey of Sec. 20 by E.A. Robinson dated June 1910, Melrose Book, Pgs. 80 & 81 and survey of Sec. 20 by E.K. Robinson dated Dec. 1881, large brown County Surveyor's Record, Liber 1, Pg. 281.

1 Estab. NW cor. of E½ of NW¼ per std. BLM instructions. A winding E-W trail rd is S 65'±

2 Estab. NE cor. of W½ of NE¼ of Sec. 21 Per std. BLM instruc. Cor. is in line w/timber line to S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9

Set DNR Mon. & Ced post
Mon. is alum. cap on 1" x 24" pipe inside 1¼" x 36" pipe over 1" x 24" pipe; all set in ced. swp. area

7" Cedar	N12°W	31.5
7" Cedar	S50°W	14.7
10" Cedar	S20°E	16.3

E-8

Set DNR Mon. & Ced. post

14" Maple	S08°E	41.6
12" Maple	S80°W	44.6
12" Maple	N50°E	53.6
Crooked Trail Rd. Curves	N45°E	13'±

1

Set 5/8" x 36" rerod w/RLS cap & ced. post

9" Maple	N80°E	18.9
7" Maple	S30°E	7.6
8" Maple	S50°W	9.4
Cor. Fn. Post (Fn. E-W-N)	N10°W	28.2

SIGNED BY Carl F. Roser 01-12-82 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET