LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. ~~S.~~, R. 5 ~~E.~~ W.	E-7, F-7, G-8, F-9
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. Continued: in 1908. We could find no evidence of Robinson's S.P cor. or his Wits; so
C. Continued: restored corner by S.P to U.S.

F-9

Set DNR Mon & ced. post
8" Maple N80°E 32.8
9" Ir. Wood (cluster) N35°E 16.3
5" Ir. Wood N55°W 30.1
Corner is on E-W Random.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-7 Recovered nail that fits MSHD Wits and MSHD tie to center of US-131 to East for NW corner of Sec. 21. Corner falls in approx. ctr. of Black Top Road to S & W.

F-7 Reestab. N 1/4 cor. of Sec. 21, on straight line bet. NE & NW cor.'s of Sec. 21 & on line across the fd. 3/4" pipe at fn. cor. at N 1/4 cor. of Sec. 16 & the fd. large rock at possible ctr. of Sec. 16; which best fits the 1/8 cor. position 1/4 mile to East and West. Local land owner says old E-W fence 32'± to North was intended as a possible R.O.W. fence years ago.

G-8 Reestab. E 1/4 cor. of Sec. 21 midway & on line between the NE & SE corners of Sec. 21. Corner falls in West berm of railroad track ballest.

F-9 Reestab. S 1/4 cor. of Sec. 21 midway & on line bet. SE & SW corners of Sec. 21. E.K. Robinson reset this corner by single proportion in 1896 & E.A. Robinson rewit. this cor.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-7
Drove 7/8" x 18" Ir. (buried 0.4')
*13" R. Pine S60°W 68.45
* P. Pole N35°E 32.70
*P. Pole brace S50°E 25.35
Ctr. of power line N. East 20'±
*=Old Wits bearing tag #21566

F-7
Set DNR Mon & ced post
6" Maple S80°W 17.3
9" Maple N25°E 8.9
5" Maple S60°E 19.3
Newer cor. fn. Post (Fn W & N) N85°W 35.3
Old E-W fence North 32'±

G-8
Set DNR Mon. (flush)
16" Maple S50°W 132.00
T. Pole N36°W 88.40
Ctr. of R.R. tracks S88°36'E 10.4'
Drove rerod w/tag & Post w/tag S88°36'E 60.00 on ¼ line
Set Pk in ctr. of US-131 N88°31'W on ¼ line 194.22

SIGNED BY Carl F. Roser 01-12-82 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL) STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION. JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET