LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 5 E. W.	L-7,K-6,L-6,M-4
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

L-6

Set 5/8" x 36" re-rod w/RLS cap & cedar post.

7" Maple	S25°E	5.9
4" Maple	S45°W	11.4
8" Maple	N60°W	24.7

M-4

Fd. DNR Mon added cedar post.

*10" BassWood (Cluster)	N85°E	10.3
*6" Maple (Twin)	S20°W	18.3
3" Maple	N35°W	14.7
5" Maple	N30°E	20.2

*=Ken Ostling old Wits

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-7 Re-estab. S¼ corner of Sec. 13 midway and on line between SE & SW corners of S-13.
K-6 Re-estab. W¼ corner of Sec. 13 midway and on line between NW & SW corners of Sec. 13.
L-6 Established center of Sec. 13 at intersection of one-quarter lines.
M-4 Fd. D.N.R. mon. as set in 1961 by Dept. R.L.S. Ken Ostling; who fd. old sq'd. stk. as recovered by M. Schaaf in the 1930's. Schaaf notes indicate he had one U.S.B.T. (stump) SW, a hemlock & line tree north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-7

Set std. DNR mon. inside 1¼"X 4' pipe & Ced. Post in Ced. Swp.

4" Cedar	S45°E	6.0
5" Cedar	N50°E	12.8
5" Cedar	N60°W	13.0
Rand. line North is West		25'±

K-6

Set DNR Mon. & Ced. Post.

22" W. Pine	S45°W	26.15
20" W. Pine	S50°E	22.94
6" Cedar	N85°E	14.2
Fd. Sq. Ced. Stk.	South	22'
Corner falls on N-S Random		

SIGNED BY Carl F. Roser 01-12-82 DATE _____

STATE OF MICHIGAN — CARL F. ROSER — SEAL — LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET