LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. ●., R. 5 ●. W.	J-5, K-5
2. PROPERTY CONTROLLING IN SECTION 13	,T. 33 N. ●., R. 5 ●. W.	2, 7, 3
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued:

7

Set 5/8" x 36" re-rod w/RLS cap & ced. post

7" Maple	S35°W	11.5
7" Maple	N80°W	21.9
7" Maple	S75°E	13.2

3

Set 5/8" x 36" re-rod w/cap & ced. post at cor. fn. post

6" Cedar	N55°E	22.50
8" Cedar	N20°E	6.62
9" Cedar	S80°W	15.92
Fd. 1¼" pipe	S56°07"E	14.89

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-5 Re-estab. N¼ corner of Sec. 14 midway and on line between the NE & NW corner of Sec.14.
K-5 Recovered 1" pipe with broken off county monument cap - old corner of record.
2 Estab. E1/8 corner on N line of Sec. 13 per std. B.L.M. instructions.
7 Estab. N1/8 corner on E line of Sec. 13 per std. B.L.M. instructions.
3 Estab. NW corner of S½-NW¼ of Sec. 13 midway and on line between the NW corner & West 1/4 corner of Sec. 13.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-5

Drove 7/8" x 18" Ir. Pin.

7" Ced	N45°W	48.8
8" Tamrack	N05°W	42.6
9" Ced.	S40°W	81.6
Ctr line E-W Blk Top Rd South		4.5'
Set Ced Post	S.	33'

K-5

Fd. 1" Pipe w/Mon cap broken off.

20" Maple	S65°E	154.10
P. Pole (brace)	S25°E	63.65
P. Pole	S30°W	61.00
Ctr line E-W Gr. Rd.	S	4'±
Ctr line N-S Gr. Rd.	E	4'±

2

Set 5/8" x 36" Re-rod w/RLS cap & ced. post.

5" Ir. Wood	N25°E	14.5
8" Maple	N35°W	14.6
5" Maple	S15°E	18.6

SIGNED BY Carl F. Roser 01-12-82 DATE _____

STATE OF MICHIGAN — CARL F. ROSER LAND SURVEYOR No. 12028 — REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

MELROSE TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET