SURVEY & ONUMENTATION

OCT 1 8 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COUNTY OF CLASSIFY	EX.
--------------------	-----

96 SEP 19 PH 4: 16

For corners in COMM	ISSION	,	Charles Charles	
_Charlevoix	Located In:	Corner Code ##	DEGISTER OF DEEDS	
Public Land Survey	T 33N R 5W T 33N R 6W	A-10 M-10		
Property Controlling in SectionMiscellaneous Property in Sec.	T R S T R S T R S T R	Record Re	egister of Deeds Stamp & File Number	
4. Lot No, I	Recorded Plat		ABCDEFGHIJK	<u> </u>
5. Private Claims			2 - 5 - 5 - 4 - 3 - 2 - 3	-
in lines 1 and 2 above were in- current manual of survey instant Management or by a decree of above were in conformance we court of Law; established, expressed below:	in a field survey on June quirements of P.A. 74, Michigan P.A. on conformance with regulations and ructions of the United States Departria Court of Law and/or that the corner ith the rules of the Michigan Board of re-established, monumented, re-motorners, all in the same town and	of 1970, the corner points mentioned if rules therefore as required in the ment of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a conumented, recovered, found as	5	-13 -24 -25
on this certificate		·	12 31 32 33 34 35	—36
A-10 /4 COMER COMMOR 1840, Township Lines by John Mul 1884, Co. Surveyor E.K. Robinson (1900±, Surveyor Unknown. Co. Sur Beech 12° S31½W 64lks. (42. 1908, Co. Surveyor E.A. Robinson, Sugar 16° N43½°W 52½lks. (1962, R. Kent (MI Hwy. Dept., Dra	lett, Set 1/2 post. Sugar 20" S24"E 16lks.(10 (Co. Survey bk. pg. 349), Fd. & Set New 3" vey bk. 119 pg. 25 copy of GLO notes alon	& M-10 Section 25, T33N-R6 1.56'), Beech 10" N23°W 19lks (12.54') Cedar Post. Sugar 20" S24°E, 16lks (10.56') g w/ New Accessories, Sugar 12" N4 Co. Survey bk. pg. 348 as an ½"x6' or 8"Maple S80"E 21.92', 5"Apple N67°E.		
■976, Granger Engineering Inc., Fd.	. %" Iron Pipe Certificate of Survey. Liber 2	38 Page 800. MSHD tag 8" Maple S58°E	31.36', tag 8" Maple S80°E 21.92', Fences South-W	/est
A-10 ¼ corner commor Fd. ¾" x 7' iron pipe Falls 0.5' West of North	n to Section 30, T33N-R5W n-South fenceline	pplied in restoring or reestablishin & M-10 Section 25, T33N-Re		
rd. nail & tag(MSHD) Fd. nail & tag(MSHD)	in 8" Maple stump, S75°E, 2 in 9" Maple, S50°E, 31.34'	1.94'		

Malo. 18-29-96

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3-10 1/2 corner common to Section 30, T33N-R5W & M-10 Section 25, T33N-R6W Ed. ¾" x 7' iron pipe, Replaced with 3" cast iron Charlevoix County Monument

Falls 0.5' West of North-South fenceline

Ed. nail & tag(MSHD) in 9" Maple, \$50°E, 31.34' Bet nail & tag in 8" Tw. Maple, S76°E, 37.58'

Set nail & tag in 4" Ash, N54°E, 35.40'

Set nail & tag in 24" Maple, N87°W, 209.51'(EDM)

Found corner is accepted as a careful and faithful perpetuation of the position of the original corner.

		•
Signed by Terry E B se	Date 6	9-29-96
Surveyor's Michigan License No339	LIBER 003 FAGE 19	FORM APPROVED BY MICHIGAN STATE #54RU OF LAND SURVEYORS, JAA. 26. REVISEU MAY 14.

Charlevoix Co. Surveyor KEPHOVED. Signature May C. Femolt