SURVEY & REMONUMENTATION

STATE OF MICHIGAN COUNTY OF CHARLEVOIX RECEIVED FOR DECORD

3/16	OCT	1	8	1996
/				

4. Lot No.

5: Private Claims \_

For corners GOMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

96 SEP 19 PM 4: 13

g nequirement of Act 74, whole P.A. 1970	
Corner Code ## REGISTER OF	DEFOR

Charlevolx (County)	Located In:	Corner Code =##	
1. Public Land Survey	т <u>33N</u> R <u>5W</u> т <u>33N</u> R <u>6W</u>	<u>A-7</u> / M-79	
	T R T R		
2. Property Controlling	S T R		
in Section	\$ T R		
3. Miscellaneous	S T R		Reg
Property in Sec.	S T R		

gister of Deeds Stamp & File Number

Control of the Contro		
Terry E. Brand in a field survey on J	une 18	, <sub>19</sub>
do hereby certify that under requirements of P.A. 74. Michig	an P.A. of 1970, the o	corner points mentioned
in lines 1 and 2 above were in conformance with regulat	ions and rules there	efore as required in the
current manual of survey instructions of the United States	Department of the	Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that th	e corner points meni	tioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan	Board of Land Surve	yors or by a Decree of a
Court of Law; established, re-established, monumente expressed below:	ed, re-monumented,	, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	В	C	D	E	F	G	H	J	K	L	М
2		 6	L		L				_		_	1
3	_	<u> </u>	<u> </u>	_		<u> </u>	Ĺ	Ш	_			
4	L	ļ 7	L.	 8	L,	ļ 9—	L,	<u> </u>	1	1	 1	2
5	L	L	<u> </u>	L				Ш	Щ		_	
6	ļ <sub>1</sub>	8	<u> </u>	 7	L-1	 6	1	5	1	4—	_,	3_
7			ļ	L	Ŀ	L_		Ш			_	
8	_1	9	2	) 0	2	1	2	2	2	3	Į	4
9	_		<u> </u>	<u> </u>	ļ	<u> </u>						
10	<b>Ĺ</b> .₃	0	L_2	9	_2	 8—	2	7—	2	6	Į	5
11	<u> </u>		<u> </u>	<u> </u>		<u> </u>	Щ	Ш	_		_	
12	3	1	3	2	3	3	3	4	<u></u> 3	5	3	6
	1	1	ı	1		1 !		ı			- 1	

A. Description of original monument and accessories and/or subsequent restoration:

## A-7 corner common to section 18 &19 T33N-R5W & M-7 Section 13 &24 T33N-R6W

1840, Twp Lines by J. Mullett, Establish Sugar 30" corner post. (no accessories establish.)

\_\_ , Recorded Plat

1841, Sub. of Twp. by C.W. Cathcart, Fd. cor. post. Hem. 10" N62°E 25lks.(16.5'), Hem. 18" \$43°E 16lks.(10.56')

1877, Co. Surveyor E.K. Robinson (Co. Surveyor Rec. pg. 335), Set cor. stake. Beech 8" N39°E 11lks. (7.26'), Beech 9" \$301/4E 24lks. (15.84')

1884, Co. Surveyor E.K. Robinson (Co. Surveyor Rec. pg.287), Fd. cor. 30" Sugar down, New B.T.s, Beech 10" N40°E 11½lks.(7.59"), Beech 10" S30½°E 24lks.(15.84"), Beech 22" S71°E 691/4lks.(45.7')

1903, Co. Surveyor E.A. Robinson (misc. bk. pg. 1), Fd. & Set Sugar post 24" w/ two pieces of plow. New B.T.s, Beech 12" N18°E 761/2lks. (50.49'), Beech 9" \$20°W 68lks. (44.88')

1928, Co. Surveyor E.A. Robinson (misc.bk.pg.1), Fd.cor.stake. Set 1½'x 36" Well pt. w/ stones. Acces. same as 1903.
1962, Surveyor R.Kent, C.R.rec.Lib.1 Pg.134, Fd.1½" I.P. Elm 12" N30°W 20.97', Elm 7" N85°W 16.05', Elm 27" S20°W 70.73', Elm 4" S10°W 25.45' 1973, Co. Surveyor M. Feindt Cert. of Survey, Rec. Lib. 229 Pg. 314, Shows cor. No description or accessories.

1979, John E. Ferguson RLS #24595 Cert. of Survey, Reo. Lib. 262 Pg. 398, Shows cor. No description or accessories.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

## A-7 corner common to section 18 &19 T33N-R5W & M-7 Section 13 &24 T33N-R6W

Fd. 3/4" pipe inside 11/2" x 36" Well point. On fenceline to West and 1' East of fenceline to North

On centerline Clute road to East and 1' East of centerline Clute road to South

Fd. stump (12" Beech), N20°E, 50.6' to face

Fd. nail & tag(#3920) in Fence post, N88°W, 33.4'

Charlevoix Co. Surveyor APPROVED

- Promer Ballion

Co. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## A-7 corner common to section 18 &19 T33N-R5W & M-7 Section 13 &24 T33N-R6W

Fd. 3/4" pipe inside 11/2" x 36" Well point. Replace with 3" cast iron Charlevoix County Monument

On fenceline to West and 1' East of fenceline to North

On centerline Clute road to East and 1' East of centerline Clute road to South

Set nail & tag in 20" Beech, N20°E, 55.67' Set nail & tag in 9" Maple, N56°E, 84.01'

Southeast corner, 4" x 6" steel "I" beam sign post, N88°W, 38.39'

Set nai & tag in Powerpole, S75°E, 149.51'

Found corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by Tury E	Brand	Date _	8-29-96	<u> </u>
signed by				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Surveyor's Michigan License No	33969	R 003 PAGE 16	FORM APPROVED BY MICHIGAN	STATE BOARD OF LAND SURVEYORS, JAN. 20, 1
· ,	LIBE	R UUSPAGE IU		REVISED MAY 14, 1