Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 33 N.R. 8 W

		Charlevo	COUNTY
DESCRIPTION OF CORNE	R Section corner common to Secti	ons 14.13.23.24	
CORNER MONUMENT	Set 2½ x 42 pipe filled with	concrete & brass ca	6" in road.
DATE MONUMENT PLACED	AND WITNESSED 12/1/67		
WITNESSES TO CORNER.	****		
N	16" W. Pine	s 68°30'r	61,001
24	14" W. Pine	N 50° 30 ° E	54.10'
+  :	8 " Cedar	s 52° 30 'W	26,001
CIRCLE CORNER REGISTS	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found ½ pipe. Set cedar post 33 West. Square top.

SURVEYOR'S SEAL

SIGNED GREGORY A. SHADKO DATE 12/12/67

REGISTERED LAND SURVEYOR X EDONAN