

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 33 N.R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner on north side Section 6, T33N, R1E

CORNER MONUMENT Set 1 1/2" x 2" pipe

DATE MONUMENT PLACED AND WITNESSED 10/25/62

WITNESSES TO CORNER.....



7" Cedar - S48W - 10.6 ft

10" Cedar - N38W - 8.6 ft

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established while making a survey in this township. Set corner by proportionate measurement between section corners, at the latitude of the standard town line.

SURVEYOR'S SEAL

SIGNED *Kenneth H. Hethcote* DATE 11/5/62  
REGISTERED LAND SURVEYOR