

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 E.
T. 33 N.R. 1 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 18 - 13

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED October 31, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

12" Cedar N 45 E 12.9'

10" Balsam S * E 15.6'

AND * Inadvertently omitted

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1 1/4" pipe in place, as established by Marcus Schaaf, R.L.S. in 1930s. Falls in center of N - S fireline. One possible BT stump SE. Best available evidence.

SURVEYOR'S SEAL

SIGNED Kenneth Postle DATE October 31, 1962
REGISTERED LAND SURVEYOR