

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 33 N.R. 1 E.  
T. 33 N.R. 1 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 6 - 1

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED October 31, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

10" Spruce S 66 W 26.7'

7" Cedar S 51 E 45.4'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement while making a survey of the meridian. Nothing positive for U.S. B.Ts. Checks fair with possible swamp edge south.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE November 26, 1962  
REGISTERED LAND SURVEYOR