## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

	T. 33	N.R. 1	Che	Cheboygan	
DESCRIPTION OF CORNER 1/4	oorner common to	Sections 30	. 25		
CORNER MONUMENT Set 1	pipe with 4" al	uminum cap			
DATE MONUMENT PLACED AND	WITHESSED Octo	ber 26, 1962			<del></del>
VITNESSES TO CORNER		- <del></del>	<del> </del>		
N		9" Spruce	n 60 B	24.91	
		8" W. Pin	e S 63 W	19.51	
	AND				

DESCRIPTION IN DETAIL AS TO NOW CORMER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners while making a survey in this township. Could locate no previous corner or U. S. evidence. Falls on east edge of N - S fireline.

SURYEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED LAND SURVEYOR DATE NOVEMBER 26, 1962