

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 33 N.R. 1 E.
T. 33 N.R. 1 W.
Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 19 - 24

CORNER MONUMENT Left 1 1/2" pipe in place at fence corner.

DATE MONUMENT PLACED AND WITNESSED October 26, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

9" Cedar S 70 E 17.8'

7" Cedar S 61 W 13.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey on the meridian. Found 1 1/2" pipe at corner, as established by Marcus Schaaf, R.L.S., in 1930s. Sites for possible U.S. BTs in place. Fence goes north and east. Best available evidence.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE October 26, 1962
REGISTERED LAND SURVEYOR