

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD


T. 33 N.R. 1 E.  
T. 33 N.R. 1 W. Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 19 - 30 - 24 - 25

CORNER MONUMENT Left 1 1/4" pipe in place 18" below surface

DATE MONUMENT PLACED AND WITNESSED October 26, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

7" R. Pine S 21 W 31.9'

7" R. Pine N 44 W 21.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1 1/4" pipe at intersection of firelines, as established by Marcus Schaaf R.L.S., in 1930s. U. S. BTs all gone.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE November 26, 1962  
REGISTERED LAND SURVEYOR