

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 W
T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 6 - 31

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-19-66

WITNESSES TO CORNER.....



7" W. Pine S 84 E 116.7'

6" B. Spruce N 3 W 83.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners during a survey in this area. No previous evidence of corner.

SURVEYOR'S SEAL

SIGNED *Levitt J. Ostlund* DATE 11-18-66
REGISTERED LAND SURVEYOR

#10068