

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 33 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to sections 22-23-26-27

CORNER MONUMENT Left 2" pipe in place

DATE MONUMENT PLACED AND WITNESSED Sept. 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Spruce N 77 W 47.8'

9" Balsam S 77 E 42.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey of this township. Found 2" pipe on north edges of new road to Cornwall Dam, as established in previous survey by Marcus Schaaf.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 11-18-66  
REGISTERED LAND SURVEYOR #10068