

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 27-28

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED Sept. 1966

WITNESSES TO CORNER.....



4" Tamarack N 80 W 5.8'

10" Cedar S 71 E 7.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township, previously located by Forestry personnel. Both original witnesses in place, dead, but showing good marks. Spruce USBT in remarkable condition.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 11 18 66
REGISTERED LAND SURVEYOR #10068