

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 W
T. 32 N.R. 1 W


Cheboygan
Otsego COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 34-35-2-3

CORNER MONUMENT Set 1" pipe with aluminum cap below surface

DATE MONUMENT PLACED AND WITNESSED 6-20-67

WITNESSES TO CORNER.....



8" W. Pine N 34 E 20.1°

12" H. Maple S 53 E 31.3°

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during partial retracement of T33-1W. Set corner in center of E-W fireline, at proportionate measurement between existing corners one mile east and west. Could not find previous corner, which was probably destroyed in construction. Checks lake shore north.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE 6-21-67
REGISTERED LAND SURVEYOR #18068