

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 33 N.R. 1 W
T. 32 N.R. 1 W Cheboygan
Otsego COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 34-3

CORNER MONUMENT Set 1" pipe with aluminum cap below surface

DATE MONUMENT PLACED AND WITNESSED 6-20-67

WITNESSES TO CORNER.....



10" Hemlock N 43 E 41.3

10" Hemlock N 19 W 34.0"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners. Could not locate anything for previous corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Osting* DATE 6-21-67
REGISTERED LAND SURVEYOR #10668