

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 26, 27

CORNER MONUMENT Left 2" pipe in place

DATE MONUMENT PLACED AND WITNESSED 7/1/67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" R. Pine N 35 E 152.25'

8" R. Pine N 17 W 134.25'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in the Cornwall Impoundment area. One original witness in fair condition. Line tree north. Fits swamp edges well north and south. Corner will be covered by Cornwall Flooding.

SURVEYOR'S SEAL

SIGNED Kenneth A. Ostling DATE 8/28/67
REGISTERED LAND SURVEYOR #10068