

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Witness corner to 1/4 corner between sections 27-26

CORNER MONUMENT Drove 1" iron pipe

DATE MONUMENT PLACED AND WITNESSED 7/3/67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Jack Pine S 57 W 20.0'

7" Jack Pine S 38 E 15.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed to preserve the position of the 1/4 corner which will be in Cornwall Flooding.

Witness corner is 2.285 North of 1/4 corner, and on line between 1/4 corner and section corner north.

SURVEYOR'S SEAL

SIGNED Louise Wittig DATE 8/28/67
REGISTERED LAND SURVEYOR
#10068