Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 3h N.R. 1 E

		Cheboygan	COUNTY
DESCRIPTION OF CORNER	1/4 corner common to Section	ons 31-32	
CORNER MONUMENT	Set 1" pipe with 4" alumin	им сар	
DATE MONUMENT PLACED AND	WITHESSED April 26, 1966		
WITHESSES TO CORNER	•		
N	7ª Cedar	N 56 E	5.21
31	6" Cedar	SIE	20.81
CIRCLE CORNER REGISTERED	AND	<u>-</u>	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored while making a survey in this township. Set corner from NW USBT which is in place with very good face.

SURVEYOR'S SEAL

SIGNED SURVEYOR #10068 DATE April 28, 1966