

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER S 1/8 corner common to Sections 17-18

CORNER MONUMENT Drove 1" x 2 1/2" pipe

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... April 27, 1966



CIRCLE CORNER REGISTERED

BT 6" Cedar S 37 E 7.2'

BT 6" Cedar S 68 W 9.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set midpoint on line between section and 1/4 corner. Bowen's 1/8 corner is about 3' west, obviously not on line between controlling corners.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE April 27, 1966
REGISTERED LAND SURVEYOR #10068