

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 E.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner on south side Section 33

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED September 14, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Balsam N 39 W 41.5'

3" Balsam N 43 E 20.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1 1/2" pipe at corner as restored by Marcus Schaaf R. L. S. in 1930s. Falls nearly midpoint on line between section corners, and is supported by sites of the possible U. S. BTs.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE October 9, 1962
REGISTERED LAND SURVEYOR