

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 34 N.R. 1 E.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner on south side Section 31

CORNER MONUMENT Set 1" pipe with aluminum cap

DATE MONUMENT PLACED AND WITNESSED August 30, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Cedar N 50 W 27.5'

6" Cedar N 32 E 24.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found 1 1/2" pipe at corner as established by Marcus Schaaf, R. L. S. Stumps in place for both U. S. B's.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Dilling* DATE October 9, 1962  
REGISTERED LAND SURVEYOR