MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

7 34 NR ± ₽

		Oneboyga	in 	_ COUNTY
DESCRIPTION OF CORN	IER 1/4 corner o	common to Sect	tions 9 and	10
DESCRIPTION OF CORNI	ER MONUMENT_	lw pipe with	t"_brass_ca	p
WITNESSES TO CORNE	R			
	7" W. Birch	- n67m	_ = 39•.	5_feet
	2" R. Pine	- 83E	72.	7_feet_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner wasestablished by Forestry Division survey crew while making a survey of Section 9. Set corner midpoint, on line between section corners. All government evidence gone, and no evidence of previous corner. This point falls about 3 south of fence lines east and west, and about 5 west of a fence that starts near here and runs southerly on a somewhat meandering course.

Corner was placed and witnessed November 11, 1959.

SURVEYORS SEAL

SIGNED LEMEL SURVEYOR DATE 11/16/59