

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 1 E

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 8-9-16-17

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place

WITNESSES TO CORNER

6" Maple - S49E - 49.5 feet
Power Pole - S47W - 48.0 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 9. Found 1 1/4" pipe in place, possibly as restored by Bowen in 1913. Falls in line with fence west and in center of N-S county road, and was considered acceptable in this survey.

Corner was witnessed November 11, 1959.

SURVEYORS SEAL

SIGNED *Kenneth Jostling* DATE 11/16/59
REGISTERED LAND SURVEYOR