SURVEY & AGMONUMENTATION

MAY 0 5 1997

RE MONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

F	?	E	C	F	1	Ų	Ē	-	D	
Fí	;					ሶ				

For	corners	in

COMMISSION

Cheboygan	Located In:	Corner Code #
(County)		
1. Public Land Survey	T34N _f TF TF	R 1W M-3 R
Property Controlling in Section Miscellaneous	S TF	
Property in Sec.	S T F	

96 NOV 25 PN 1:03

CLERK/REGISTER CHEBOYGAN COURTY, MICHIGAN

Register of Deeds Stamp & File Number

	Private Claims	orded Plat	
I,	Brian K. Fullford	_, in a field survey on	_, 19 do hereby state that under
confe Unite	ormance with regulations as	gan P.A. of 1970, the corner points men nd rules therefore as required in the curre a Interior, Bureau of Land Management of	tioned in lines 1 and 2 above were in

hat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A_	В	Ç	D	E	F	G	Н	I	J	ĸ	L	١
				1				1			1	7	_
2		6	\top	-5- I	十	- 4 —	十	· 3	+	2-	+	1-	_
3	-	+		+-	+	+	+	 	+	┼	+	-	-
4	\vdash	-	+	- 8 -	 -	. 9_	+-	10-	 - -	 11—	-	12-	
5	\vdash	-	+-	+	+	+	+-	+	┼-	+	┼-	+	
6	 	1,8—	+	-17-		16		·15—	 	1 14—	 	 13–	
7	L	1_	\perp		1	1_				<u></u>			
8	-:	19_	_	-20 <u>-</u>	<u> </u>	 21	ļ	22_] 23_		24_	
9	_	_	\perp	+	\downarrow	\bot	-	1	_	_	-	1	
10	-	30—	_	-2 9	-	28	\bot	27	↓_ 2	 26	 2	 25	_
11	<u> </u>	├-	+	+	+-	\bot	-	╀-	ļ	_	<u> </u>	_	
12	-3	1 31	- -	-3 ²	₩:	33	igaplus	34	Щз	 }5	<u> </u> -3	[36⊸	
• •			1		1	1		1	ĺ	1		i	

A. Description of original monument and accessories and/or subsequent restoration:

Set Section Corner 8" Beech S31°W 9 Links 7" Beech N12°E 18 Links

1951 D.O.C. Corner Record Dean DeLamater #5778 Set 1" Pipe w/4" Brass Cap 8" H. Maple N70°W 26 Links 7" H. Maple S33°E 103 Links

1973 Recorded Survey Liber 343, Pages 450 & 451 Delmer Porter #15410 **Fnd Conservation Monument** 8" H. Maple N80°E 21.30' 12" H. Maple N65°W 16.22"

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Fnd 1" Pipe With Department of Conservation Brass Cap
Fnd 8" H. Maple N71°W 17.03' (DeLamater Witness)

Fnd 8" H. Maple N83°E 21.50' (Porter Witness)

Fnd 5" Maple S66°W 2.05' (Porter Tag)





	Description of monument for corner and accessories			
•	pescription of monunitation collecting accessories	established to	1 Narnetusta locatina tha masiiss	

Fnd 1" Pipe with 4" Department of Conservation Brass Cap. Accepted as a careful & faithful re-M-3 establishment of the position of the original corner.

21" Maple N40°E 23.90' Set Tag 9" Maple Clump N83°E 21.90' Set Tag 5" Maple S66°W 2.05' Tag #15410 8"/12" Tw. Maple N71°W 17.03' Set Tag

Marin a Ra

2 5 1996

gan Count

THIS CORNER IS ALSO DESIGNATED AS CORNER CODE #A-3, IN T34N-R1E.

igned by

Wonumento

urveyor's Michigan License No Brian K. Fullford, PS