

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to sections 19-20-29-30

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-19-66

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" B. Ash S 30 W 15.5'

12" W. Birch N 36 E 22.3'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of this township. Found 1½" pipe in place, as established by Marcus Schaaf, RLS in a previous survey of this township.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Osting* DATE 11-18-66
REGISTERED LAND SURVEYOR #10068