

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 19 - 20 - 29 - 30

CORNER MONUMENT Set 1" x 24" pipe below surface

DATE MONUMENT PLACED AND WITNESSED June 26, 1962

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

9" Spruce N 62 E 35.0'

6" Cedar S 11 E 48.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found a cedar stake at corner with piece of old crosscut saw alongside, in line with roads N - E - W, below surface.

SURVEYOR'S SEAL

SIGNED *Leuech Wetling* DATE June 26, 1962
REGISTERED LAND SURVEYOR