MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, midpoint on line, between section corners while making a survey in this area. Could find no previous corner and no positive original evidence. Falls near center of E-W fireline.

SURVEYOR'S SEAL

SIGNED Kenneth Kalling DATE 11/5/62
REGISTEPED LAND SURVEYOR