

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N. R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 22-23

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED June 16, 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

1 1/4" R. Pine S 47 W 73.7'

1/4" R. Pine N 50 W 12.4'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found old squared post at corner probably as established in 1930 survey by Schaaf. Fits proportionate measurement exactly.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE June 20, 1966
REGISTERED LAND SURVEYOR #10068