

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N. R. 1 W
T. 34 N. R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 36 - 31

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8-31-66

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

12" R. Pine S 13 W 28.4'

6" J. Pine N 65 E 26.7'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found 1 1/2" pipe in concrete at corner as established in 1938 survey by Marcus Schaaf, RLS. Fits good for midpoint on line between section corners. One possible USBT stump in place.

SURVEYOR'S SEAL

SIGNED Kenneth Postling DATE Nov. 18, 1966
REGISTERED LAND SURVEYOR #10068