

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 23 - 26

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED August 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

14" R. Pines N 29 W 15.1'

14" R. Pine N 48 E 8.7'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey of this township. Corner previously restored by Marcus Schaaf RLS. Remains of original witness trees evident, but in poor condition.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 11-18-66
REGISTERED LAND SURVEYOR #10068