Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 34 N.R. 1 W

		Cheboygan	COUNTY
DESCRIPTION OF CORNERSe	ction corner common to see	ctions 13-14-23-2	4
CORNER MONUMENTSe	t l" pipe with 4" aluminu	m cap	
DATE MONUMENT PLACED AND WITH	IESSED August 1966		
WITHESSES TO CORNER			
N	6" W. Pine	N 80 W	21,21
<u></u>	5" R. Maple	N 10 W	29.91
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township. Found 1 iron bar and fence post in line with old fence west. Falls in line with old road east, check U.S. notes to stream north and fits existing corners west.

SURVEYOR'S SEAL

SIGNED MCCUELLY DELLING DATE 11-18-66