MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T..34. NR.1.# ..

			CheboyganCOUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 2, 3, 10, 11
DESCRIPTION	OF	CORNER	MONUMENT_1= Pipe with 4=Brass cap
WIT TNESSES	то	CORNER	-8# -MBirch N-48 -M 91 Links
			_8F_W_ BirchE_30 E = 26_Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by double proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this Township. Burned over land, no original evidence.

Corner was placed and witnessed November 9, 1951.

SURVEYORS SEAL

SIGNED SEEM C. SURVEYOR DATE 12/6/51 -