MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.__34 NR_1_#__

			CheboygenCOUNIN
DESCRIPTION	OF	CORNER	Section Corner common to Sections 22,23,26,22 27.
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4"_Brass cap
WIT TNESSES	то	CORNER	6*_SpruceN_87-E = 29 Links
			125 J. Pine6_43 Y = 33 Tinks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Corner had been previously located and perpetuated by unknown surveyor. Two original B.T.'s in place, badly burned.

Corner was placed and witnessed July 24, 1951.

SURVEYOR'S SEAL

SIGNED Sem C. Sule Date 7/25/51_
REGISTERED LAND SURVEYOR