

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34. NR. 1 W.

----- Cheboygan ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 28, 29, 32, 33 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 10" Cedar - N 50 W - 37 Links -----

12" Cedar - N 28 E - 19 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew, while working in
this area. One original B.T. in place, in poor condition. Corner is in edge of small
stream bed.

Corner was placed and witnessed August 1, 1951.

SURVEYORS SEAL

SIGNED Gene C. DeLoater DATE 8/1/51
REGISTERED LAND SURVEYOR